



2025年4月25日科研楼实验室安全隐患排查、卫生 巡查异常情况通报

2025年4月25日科研中心教职工对第五实验楼、第二实验楼五六楼、第四实验楼一二楼科研实验室进行安全隐患排查及卫生检查，检查结果如下：

序号	日期	存在问题	所在位置	照片
1	4.25	烘箱上有物品	第五实验楼 205	
2	4.25	未穿实验服	第五实验楼 317	
3	4.25	无使用登记本	第五实验楼 511	

4	4.25	实验台有 水杯	第五实验楼 610	 <p>第五实验楼610实验台有水杯</p>
5	4.25	实验台有 水杯和饮 料	第五实验楼 608	 <p>五实验楼608实验台有水杯和饮 料</p>
6	4.25	垃圾未及 时清理	第五实验楼 520	 <p>第五实验楼520垃圾未及时清理</p>

7	4.25	试剂瓶、纸箱摆放凌乱	第五实验楼 612	 <p>第五实验楼612试剂瓶, 纸箱摆放凌乱</p>																																												
8	4.25	烘箱使用未登记	第二实验楼 611	 <p>使用记录</p> <table border="1" data-bbox="823 761 1174 1137"> <thead> <tr> <th>使用日期</th> <th>使用时间</th> <th>操作人员 (姓名、电话、项目、组别)</th> <th>使用记录</th> </tr> </thead> <tbody> <tr> <td>2023/4/25</td> <td>9:00-10:00</td> <td>史志平</td> <td>✓</td> </tr> <tr> <td>2023/4/25</td> <td>9:00-10:00</td> <td>史志平</td> <td>✓</td> </tr> <tr> <td>2023/4/25</td> <td>9:00-10:00</td> <td>史志平</td> <td>✓</td> </tr> <tr> <td> </td> <td> </td> <td> </td> <td> </td> </tr> <tr> <td> </td> <td> </td> <td> </td> <td> </td> </tr> <tr> <td> </td> <td> </td> <td> </td> <td> </td> </tr> <tr> <td> </td> <td> </td> <td> </td> <td> </td> </tr> <tr> <td> </td> <td> </td> <td> </td> <td> </td> </tr> <tr> <td> </td> <td> </td> <td> </td> <td> </td> </tr> <tr> <td> </td> <td> </td> <td> </td> <td> </td> </tr> </tbody> </table> <p>第二实验楼611烘箱使用未登记</p>	使用日期	使用时间	操作人员 (姓名、电话、项目、组别)	使用记录	2023/4/25	9:00-10:00	史志平	✓	2023/4/25	9:00-10:00	史志平	✓	2023/4/25	9:00-10:00	史志平	✓																												
使用日期	使用时间	操作人员 (姓名、电话、项目、组别)	使用记录																																													
2023/4/25	9:00-10:00	史志平	✓																																													
2023/4/25	9:00-10:00	史志平	✓																																													
2023/4/25	9:00-10:00	史志平	✓																																													
9	4.25	烘箱未登记	第二实验楼 520	 <p>电热鼓风干燥箱</p> <p>26 °C</p> <p>6.0</p> <p>第二实验楼520烘箱未登记</p>																																												

10	4.25	烘箱未登记	第二实验楼 614	 A photograph of a laboratory oven. The oven is white with a black viewing window and a control panel on the left side. A red label is affixed to the top of the oven, reading "614烘箱未登记" (614烘箱未登记). The oven is situated on a laboratory bench. In the background, a person in a white lab coat is visible, and various laboratory equipment and supplies are scattered on the bench.
----	------	-------	--------------	---